

Technote 165: topsize() error

Error: topsize(): AP2 not ready to receive command.

This error typically appears in the S232 Controller when the D/A- A/D test is run. It is due to the corruption of AP2 memory. This error is *not* fixed by restarting or shutting down the computer. The only fix for this error is to fully reset the AP2 memory by pulling the AP2 card out of the computer and then reinserting it. This problem should only rarely occur (in most cases, it will not recur). If it happens often, contact TDT Technical Support.