

Technote 166: DB4 Ace! Error

DB4 Biological Amplifier Controller display shows ACE!

This is generally caused by a communication problem with the HS4.

Troubleshooting:

1. Check that the batteries in the HS4 are fresh.
2. If the lights also repeatedly cycle on the HS4, it is possible that the EEPROM is bad. Contact TDT Technical Support (support@tdt.com) for information on getting a new EEPROM.