

## **Tech Note 174**

**Issue:** System II S232 Controller and Windows XP Service Pack1.

**Summary:** The WindowsXP Service Pack1 security patches seem to affect the functioning of the S232 Controller.

**Workaround:** When using Windows XP and Service Pack 1, install all the required critical updates except for the security patches.