

Tech Note 174

Issue: System II S232 Controller and Windows XP Service Pack1.

Summary: The WindowsXP Service Pack1 security patches seem to affect the functioning of the S232 Controller.

Workaround: When using Windows XP and Service Pack 1, install all the required critical updates except for the security patches.